



DrDepth

Sea bottom mapping software

Shortcuts

Back

Help

BT Help

Connect

SS Help

Adjust range

q Min up
w Min down
e Find range
r Max up
t Max down
u Range up
d Range down
 Hold down **Shift**
 to adjust in steps
 of 5 units

3D on/off

3D resolution

Zoom

Page up, p, +
 Zoom in
Page down, m, -
 Zoom out

Arrow keys

2D Pan
3D Rotation
Edit move:
Left Back
Right Forward
Down Delete

Pan to map center

Mark wpt

Add

DB manager

Wpt manager

Update labels

Settings

Re-center

Background map

Mouse functions

Double click Open waypoint
Ctrl – Double click Create waypoint
Shift – Double click Trace raw data
Alt – Double click Set measurement tape
Right Ctrl – Double click Select single contour

(Menu) function key modifiers

Shift – File/Add Set file type selector to .drr
Ctrl – File/Add Set file type selector to .ddb
Shift – Tools/Clear Area Clear area outside polygon
Ctrl – Tools/Clear Area Use file as area delimiter
Ctrl – g Background map settings
Shift – DB manager Reload active database